

## SERVICE NOTE

EFFECT: 2AXXON

004

NUMBER:

7/7/82

The following list is our Recommended Spare Parts for the support of ten (10) games:

ITEM NO.	PART NO.	QTY.	DESCRIPTION	COST
1.	834-0236	1	ASSY, Joystick	\$40.00
2.	390-0003	3	LEO	.35
3.	270-0001	1	FILTER, EMI	10.00
4.	150-0009	5	CAP, E 1 MF 50V	. 25
5.	150-0023	3	CAP, E 10MF 16V	2.00
6.	150-0100	3	CAP, E 2.2MF 50V	.20
7.	150-0160	3	CAP, E 470MF 16V	.18
8.	151-0073	10	CAP, C .047MF 25V	.25
9.	152-0033	5	CAP, F .01MF 50V	.06
10.	313-0034	2	IC, LM324 M/C	.65
11.	313-0084	1	IC, MB4391M	1.90
12.	313-0097	1	IC, LA4460	1.55
13.	313-0110	1	1C, MB3761	9.00
14.	315-0033	1	IC, C04016	- 35
15.	315-0041	1	IC, 280A (MK-3880-4)	22.50
16.	315-0125	1	1C, MB8128-15	7.35
17.	315-0152	1	1C, 8255AC-5	3.20
18.	230-0043	1	XTAL, 48.660 MHz	1.00
19.	314-0019	2	IC, 74LS04	.50
20.	314-0016	2	IC, 74LS20	-43
21.	314-0070	2	IC, 74LS86	.60
22.	314-0076	2	IC, 74LS157	. 36
23.	314-0097	1	1C, 74LS161	.80
24.	314-0073	2	IC, 74LS175	.65
25.	314-0100	1	1C, 74LS273	1.28
26.	314-0101	3	IC, 74LS283	1.25
27.	314-0122	2	1C, 74LS299	2.76
27a	109-0059	1	HOLDER, Joystick Spri	ng .30

TEM NO.	PART NO.	QTY.	DESCRIPTION	COST
	MC-	2000-S 191	NANAO MONITOR	
28.	482-0257	3	XISTOR, 2SC2688	\$ .5
29.	482-0111	2	X15TOR, 2SA673	.4
30.	482-0271	2	XISTOR, 2SC2555	- 9
31.	482-0201	2	XISTOR, 2SD763	. 4
32.	482-0167	2	XISTOR, 2SC2482	.5
33.	313-0051	1	IC, HA11235	2.3
34.	560-0100	1	XFMR, MSH1FACO2	11.0
	19K467	5 19" WELL	S/GAROENER MONITOR	
35.	482-0290	2	XISTOR, 2SC1514	.8
36.	482-0261	2	XISTOR, 2SC1740Q	3.1
37.	482-0288	2	XISTOR, 2SC1454	4.0
38.	482-0284	2	XISTOR, 2SA490	2.6
39.	482-0285	2	XISTOR, 2SC1625	5.4
	G07-9	07 19" ELE	CTROHOME MONITOR	
40.	560-0096	1	XFMR, Flyback	17.0
41.	482-0198	2	XISTOR, 2,50870	2.7
42.	482-0143	3	XISTOR, 2SC1106A	2.6
43.	482-0196	2	XISTOR, 250478	.5
44.	482-0290	2	XISTOR, 2SC1514	.8
45.	482-0111	2	XISTOR, 28A673(C)	. 4
46.	482-0177	2	XISTOR, 2801685(R)	.3
47.	316-0807	1	1C, HA11244	1.4